

The Standard A RCRAFT LOG

Book 2 10/17/2013

ASA-SA-2

MAKE CESSANA MODEL 7210L S/N 21061437 REG NO N732DQ WORK ORDER P1341



Repair Station No. K5SR339N 303 N 2370 W Salt Lake City, Utah 84116 Phone: 801-933-7500 DATE 10/17/2013 A/C TSN TACH 2887.9 tes

Airframe Entries

(1) CARGO DOOR LEAK REPAIRED BY INSTALLING NEW RIVETS ON HINGE AND REATTACHED SEAL.

(2) REPLACED SEALS ON FRONT OF BAFFLE AND ADJUSTED BAFFLE SEALS ATTACHED TO COWL

(3) NLG OLEO STRUT RE PACKED WITH P/N: TCNS1. SERVICED WITH NITROGEN AND 5606 HYDRAULIC FLUID. WORK DONE IAW CESSNA 210 MM CH:1J15. LEAK CHECK SATISFACTORY.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Keystone Aviation LLC Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repair are on file under Work order No. P1341

DATE: 10/17/2013

SIGNED:

Certified Repair Station No K5SR339h

Work Order: P1341

Printed by EBis 3 (datcomedia.com)

MAKE CESSANA MODEL T210L S/N 21061437 REG NO N732DQ WORK ORDER P1377



Repair Station No. K5SR339N 303 N 2370 W Salt Lake City, Utah 84116 Phone 801-933-7500 DATE 10/31/2013 A/C TSN TACH 2896.1

Airframe Entries

(1) PROPELLER DE-ICE BOOT REMOVED AND REPLACED WITH NEW DE-ICE BOOT P/N 6199SW PER CESSNA 210 SERVICE MANUAL SECTION 15-16. OPERATIONAL CHECK SATISFACTORY.

(2) L/H EXTERIOR DOOR HANDLE REMOVED AND REPLACED WITH NEW HANDLE P/N 0517003-2 PER CESSNA AMM

3-27A, AND 3--27B P. 3-7. OPERATIONAL CHECKED SATISFACTORY.

(3) CESSNA SERVICE BULLETIN SEB07-5 R2, PILOT AND CO-PILOT SECONDARY SEAT STOP INSTALLATION, C/W ON PILOT SEAT ONLY BY INSTALLATION OF KIT P/N SK210-174B. OPERATIONAL CHECK SATISFACTORY.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Keystone Aviation LLC Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) and/or maintenance performed and is approved for return to service as per those requirements. Pertinent details of the repair are on file under Work order No. P1377

DATE: 10/31/2013

SIGNED:

Scott L. Goodfellow Certified Repair Station No. K5SR339N Work Order: P1377

Printed by EBis 3 (datcomedia.com)

Model: Cessna T2	210L			Tach: 2928.0			
S/N: 21061437 Reg# N732DQ				TTA: 2928.0			
Reg 14752DQ							
Cari i							
C/W Annual insper	ection IAW Cessna 21	0 Maintenance Manual & Single	Engine Inspection Guide. C/V	W FAR 91.207(d) 1-4 ELT ops check			
requirements. 140	ucicus noted. Replace	ed E1.1 panery next due (a) 03-2	015 C/W AD 2011 10 00 Do-	(g)1-10 by inspection and measurement of the 9-07 R1 IAW PAR (a)1. No cracks detected.			
and the state of t	THE THAT SOUND OUT	v. Replaced induction air filter i	A- /Alla Rebuilt lett and make	broke selin D 1 11 0 11 0			
***************************************	-02. Replace left blake	e line at camper Bled left and rio	ht broker (Incohook good Da	-1			
- ac compinated to	5, an AD are current	see AD list. Performed routine see with FAR Part 43 Appendix D	ervicing and maintenance Rui	n un one and look about - 1 T			
The aircraft, airtrame	, aircraft engine, propelle	r or appliance identified above was re	naired and inspected in asserdance				
approved for return to	service. Pertinent detail	s of the repair(s) are on file at this Fa	cility under the above referenced W	Verk Order.			
				111.1			
Date: July 18, 2014			Inspector: Scott Wilson 3142227IA				
				GCOR WISON 314222/1A			
	MAKE CESSANA	KEVSTONI	Repair Station No. K5SR339N	DATE: 2/17/2014			
	MODEL T210L S/N. 21061437	KEISTON	303 N 2370 W Salt Lake City, Utah 84116	A/C TSN TACH: 2908.3			
	REG. NO: N732DQ WORK ORDER: P1522	* AVIATION	J Phone 801-933-7500				
	Airframe Entries	a state of the sta					
		OOR LATCH STAYING OPEN TR	DUBLESHOT FOUND DOOR	PUSH ROD BENT. INSTALLED NEW			
	(1) TROUBLESHOT DOOR LATCH STAYING OPEN TROUBLESHOT. FOUND DOOR PUSH ROD BENT. INSTALLED NEW BOLT PUSH ROD P/N 0517021-4. PER CESSNA AMM SECTION 3, FIG 3-4 AND 3-5. OPS CHECK SATISFACTORY.						
1	certify the airframe, engine	e and/or component identified herein was	repaired and inspected in accordance	e with the current Keystone Aviation LLC Repair			
	Manual System and the Fed	deral Aviation Regulations under which th	e operator is certified, and was deter-	mined to be in an Airworthy Condition at this to service as per those requirements. Pertinent			
		ile under Work order No. P1522	A []	to service as per trose requirements, i orange.			
	DATE: 2/47/2044	SIGNED	144	Work Order: P1522			
	DATE: 2/17/2014	SIGNED: W	my v-vay				
		Jimmy P. Ray Certified Repair Station No. K	5SR339N ()	Printed by EBis 3 (datcomedia.com)			
	1						
The state of the s	THE PARTY OF THE P						

NSF

S/N: 21061	ssna T210L				
Manager Company of the Company of th					Tach: 2968.6
D HATMAN					TTA: 2968.6
Reg# N732	ZDQ				1111 250010
C/W Annu	ual inspection IAW	Cecena 210 Maintanas	200 Manual & Si - 1 E		
requiremen	nts No defects note	d Replaced El Thatte	ice Manual & Single El	ngine Inspection Guide. C	W FAR 91.207(d) 1-4 ELT ops check
rail ceat ro	aller housing and tar	or Nevt due @ 2029	O took or next Assess	C/W AD 2011-10-09 Par.	(g)1-10 by inspection and measurement of the sea
Inspection)	dated 11/26/86 IA	W PAR (a)1 No crack	e detected Depleced A	Complied with AD/1-09-1	77 R1 (Engine Exhaust System/Heat Exchanger
tires Renai	ired hole in right co	wling Replaced Centr	ol air filter D/M D A 111	0.1 Deplement 1 -0	S/N G02915409. Rotated Left and right main av light 7512-24. Replaced Tail Beacon Lamp P/N
T28V150V	V Installed overhau	led Engine Overhaul	ar all litter F/N KA-131	Wood Green High Book	av light /512-24. Replaced Tail Beacon Lamp P/N
strainer Re	enlaced fittings ANS	216-2D and ANS22-21	Deplese Throttle Co.	, wood Cross Utan. Replace	ced Fuel Line P/N 1200406-100. Rebuilt fuel sump
Danlaced D	Propeller Control Co	ble D/N (200506 010	1. Replaced Ped Ends	itrol Cable P/N C299505-1	01. Replaced Mixture Cable P/N C299507-0101.
Welding for	or Overhoul and Ma	diffication Panlaced at	1. Replaced Rod Ends	on all three Control Cables	, P/N S1104-3. Exhaust System was sent to Knisle
Installed O	verhauled Weist as	to D/N 470000 11 CAL	VCD0112 Porload I	cis. Installed Overnauled	Turbocharger P/N 406610-9005 S/N EBO105.
SALL EDO	112 Danlaged Valle	/Hartrall Controller	KGRUITZ. Replaced K	elly/Hartzell Pressure Reli	ief Valve with overhauled unit, P/N 470930-9001
S/IN LERUI	fold procesure to 22	" Perland all Engin	in Overnauled Unit, P	/N 470688-0005 S/N KGN	00427. Made miner adjustment on controller to
oring mani	a log all AD are our	. Replaced all Engin	e Hoses Firewall Forw	ard with Aeroquip 303 Hos	se, 491 hose fittings and fire sleeve. Completed Al
				nnual inspection and deter	p, ops and leak checks good. I certify that this
COLUMN TWO IS NOT THE OWNER.	NAME AND ADDRESS OF THE OWNER, WHEN PERSON NAMED IN		NAME OF TAXABLE PARTY.	CONTRACTOR OF THE PROPERTY OF	ce with current Federal Aviation Regulations and is
approved for Date: May		tinent details of the repair	(s) are on file at this Facili	ity under the above referenced Inspe	ector: Scott Wilson 3142227IA

